

## Register Post Acknowledgement Due

Office of the Executive Engineer,  
Chandanagar Circle-21,  
Serilingampally Zone: GHMC

Ph: No. 040-23033163, Fax.No. 040-23033162, e-mail:ID:eed12.ghmc@gmail.com

**From**

The Executive Engineer,  
Chandanagar Division-21,  
SLP Zone, GHMC.

**To**

Vasanthi Parasuram  
Maharishi Vidya mandir  
Kondapur, HYD.

**Lr.No.EE/GHMC/DIV-21/2021-22**

**Dated:31.05.2021**


**Sub:** GHMC - Engg - SLP Zone -Division-21- Building structural report of Maharishi vidya mandir, Girish park, Kondapur -Report submitted- Reg.


**Ref:** Request letter from the principal of Maharishi Vidya mandir Dated:21.05.2021

-oOo-

Vide reference 1<sup>st</sup> cited, the principal of Maharishi Vidya mandir which was constructed on 28.03.2010, requested for the Building structural report of Maharishi vidya mandir, Girish park, Kondapur to renew the affiliation of school.

In this connection, concerned Dy.EE and AE-Madhapur ward-107, Chandanagar circle-21 inspected the site and observed visually that the structure is a RCC framed. We have thoroughly inspected the said building and found that no adverse indications about the structural weakness or impairment of the buiding. I herby certify that the above said structure is structurally sound and safe for residential and school running purpose.

  
PRINCIPAL  
MAHARISHI VIDYA MANDIR  
Girish Park, Kondapur,  
R. R. Dist. Hyd-500 084

  
EXECUTIVE ENGINEER  
CHANDANAGAR CIRCLE-21  
SLP.ZONE, GHMC  
